

Critical lap speed

It is necessary to check if the ball screw rotation speed is lower than the critical lap speed. We recommend 80% or less of the critical lap speed as rotation speed. The diagram below summarizes the allowable rotation speed. Select the allowable speed according to the method of supporting the ball screw.

